K02217J2404

U-car Grading Report

CERTIFICATE OF GOO KANTEI

This is to certify that the car specified below was inspected and rated without prejudice or influence in a fair manner, in accordance with the standards stipulated by Japan Automobile Appraisal Association. This inspection and rating was conducted by inspector officially appointed by PROTO Malaysia Sdn Bhd.

SPECIFICATIONS

MODEL	PROTON EXORA		
COLOUR	Champagne colour		
MODEL YEAR	-	METERED MILAGE	65,153Km
TYPE		CHASSIS NO.	PL1FZ6YDRCF078308
NOTE	Not flooded		

RATING

EXTERIOR	★★★★	There are damages which are smaller than A4-size sheet and/or width. Defects on the bodywork due to repairs and/or damages smaller than a card in length and/or width can be seen on more than 4 areas of the bodywork.
INTERIOR	★★★	Acceptable condition but with some areas showing damage or are worn out excessively. There may also be damage such as stains, cigarette burns or tears/ cuts on the seat fabric or interior surfaces.
FRAME	Excellent Condition	No apparent damage was found.
ENGINE	Good condition	Nothing irregular was found.

DATE OF INSPECTION	24 October, 2017
OUTLET	DOMINATING CYG MOTOR SDN BHD (1186982U)
ADDRESS	

The inspection of the car was conducted without driving it. No driving test was carried out. This certificate indicates the status of the car as of DATE OF INSPECTION and does not guarantee the quality of the car onwards. The status of the car may change after the date of inspection and it is strongly recommended that you should check the car with the car seller by yourself.

Goo KANTEI was:
Certified by JAAA

JAAA
Japan Automobile Appraisal Association

PROTO MALAYSIA

NOTE OF CONDITIONS

DATE OF INSPECTION	24 October, 2017		DATE OF RE-INSPECTION		

RATING	EXTERIOR	★★★★	INTERIOR	★★★	FRAME	Excellent Condition	ENGINE	Good condition

DESCRIPTIONS

SS	Smaller than a coin	S	Smaller than a card	M	Smaller than an A4-size sheet
L	Larger than an A4-size sheet	Few	Equal or less than 6 points	Many	More than 7 points





＜Note＞
Entire part of exterior Re-painted
Noticeable Re-painted mark

＜Window＞
Front windscreen Stone chip Partial

＜Interior＞
Luggage room Dirt or Scratch Partial
Shift knob Wrinkle/Scratch Exist
Headliner Wrinkle S
Headliner Dirt S

QR for the Report of CP Diagnosis.

http://npo-jaaa.or.jp/en/download/

The description above was based on the status of the car as of DATE OF INSPECTION.
RATING above may differ from any other Inspection conducted by other inspection organizations.