



# U-car Grading Report

## CERTIFICATE OF Motor Trader Inspection

This is to certify that the car specified below was inspected and rated without prejudice or influence in a fair manner, in accordance with the standards stipulated by Japan Automobile Appraisal Association. This inspection and rating was conducted by inspector officially appointed by PROTO Malaysia Sdn Bhd.

### SPECIFICATIONS

MODEL	HONDA HR-V		
COLOUR	Silver		
MODEL YEAR	-	METERED MILAGE	50,996Km
TYPE	CHASSIS NO.	PMHRU5830FD500876	
NOTE	Not flooded		

### RATING

EXTERIOR	★★★★	There are damages which are smaller than A4-size sheet and/or width. Defects on the bodywork due to repairs and/or damages smaller than a card in length and/or width can be seen on more than 4 areas of the bodywork.
INTERIOR	★★★★	Good condition but with some areas showing damage or are worn out excessively
FRAME	Excellent Condition No apparent damage was found.	
ENGINE	Good condition Nothing irregular was found.	
DATE OF INSPECTION	1 March, 2018	
OUTLET	HO YEE AUTO SDN BHD (884200-P)	
ADDRESS		

The inspection of the car was conducted without driving it. No driving test was carried out. This certificate indicates the status of the car as of DATE OF INSPECTION and does not guarantee the quality of the car onwards. The status of the car may change after the date of inspection and it is strongly recommended that you should check the car with the car seller by yourself.  
Motor Trader Inspection is Certified by JAAA.



### NOTE OF CONDITIONS

DATE OF INSPECTION	1 March, 2018	DATE OF RE-INSPECTION						
RATING	EXTERIOR	★★★★	INTERIOR	★★★★	FRAME	Excellent Condition	ENGINE	Good condition

### DESCRIPTIONS

SS	Smaller than a coin	S	Smaller than a card	M	Smaller than an A4-size sheet
L	Larger than an A4-size sheet	Few	Equal or less than 6 points	Many	More than 7 points
Exist Mark from metal work SS Dent	Exist Mark from metal work	Exist Mark from metal work Few SS Scratch	Exist Mark from metal work	< Window > Front windscreen Stone chip Partial	< Interior > Other trim Scratch Partial
3 Ditch level			3 Ditch level S Shaved/Scratch		
Exist Mark from metal work			Exist Mark from metal work Exist Scratch on edge		
Exist Mark from metal work Few SS Scratch			Exist Mark from metal work		
5 Ditch level S Shaved/Scratch			5 Ditch level M Shaved/Scratch		
Exist Mark from metal work Few SS Scratch/Dent			Exist Mark from metal work		
		Few SS Scratch/Dent	Exist Mark from metal work		
			S Wrinkle/Scratch		
			M Wrinkle		

QR for the Report of CP Diagnosis.



<http://npo-jaaa.or.jp/en/download/>

The description above was based on the status of the car as of DATE OF INSPECTION.  
RATING above may differ from any other Inspection conducted by other inspection organizations.