

U-car Grading Report

CERTIFICATE OF Motor Trader Inspection

This is to certify that the car specified below was inspected and rated without prejudice or influence in a fair manner, in accordance with the standards stipulated by Japan Automobile Appraisal Association. This inspection and rating was conducted by inspector officially appointed by PROTO Malaysia Sdn Bhd.

SPECIFICATIONS

MODEL NISSAN X-TRAIL

COLOUR Silver

MODEL YEAR - METERED MILAGE 21,020Km

TYPE CHASSIS NO. PN8JAAT32TCA24230

NOTE Not flooded

RATING

EXTERIOR ★★★★★ There are damages which are smaller than A4-size sheet and/or width. Defects on the bodywork due to repairs and/or damages smaller than a card in length and/or width can be seen on more than 4 areas of the bodywork.

INTERIOR ★★★★★ Good condition but with some areas showing damage or are worn out excessively

FRAME Excellent Condition No apparent damage was found.

ENGINE Good condition Nothing irregular was found.

DATE OF INSPECTION 1 March, 2018

OUTLET HO YEE AUTO SDN BHD (884200-P)

ADDRESS

The inspection of the car was conducted without driving it. No driving test was carried out. This certificate indicates the status of the car as of DATE OF INSPECTION and does not guarantee the quality of the car onwards. The status of the car may change after the date of inspection and it is strongly recommended that you should check the car with the car seller by yourself.
Motor Trader Inspection is Certified by JAAA.

NOTE OF CONDITIONS

DATE OF INSPECTION	1 March, 2018	DATE OF RE-INSPECTION			
RATING	EXTERIOR ★★★★★	INTERIOR ★★★★★	FRAME Excellent Condition	ENGINE Good condition	
DESCRIPTIONS					
SS	Smaller than a coin	S	Smaller than a card	M	Smaller than an A4-size sheet
L	Larger than an A4-size sheet	Few	Equal or less than 6 points	Many	More than 7 points
	Partial Stone chip	Few SS Scratch			< Window > Front windscreen Stone chip Partial
3 Ditch level			3 Ditch level		< Interior > Luggage room Dirt or Scratch Partial Shift knob Wrinkle/Scratch Exist
Exist Mark from metal work			Exist Mark from metal work Exist Scratch on edge		
Exist Mark from metal work			Exist Mark from metal work		
3 Ditch level			3 Ditch level		
Few S Scratch			Exist Mark from metal work		
		Few M Scratch			
			S Wrinkle/Scratch		
			M Wrinkle		

QR for the Report of CP Diagnosis.



<http://npo-jaaa.or.jp/en/download/>

The description above was based on the status of the car as of DATE OF INSPECTION.
RATING above may differ from any other Inspection conducted by other inspection organizations.